

How-to guide

Loss of Inverter 240v power

Symptom:

No 240v power in your caravan inverter.

Cause:

Inverter RCD trip

Inverter wiring loose

Faulty wiring or defect

What to do:

If your caravan is fitted with an Enerdrive inverter, check the black plug in cables are fully slotted in. These cables can become loose in transit. Your inverter may also be fitted with an RCD which can be found on short end of the inverter. Ensure this is not tripped.

Please note that if the RCDs continue to trip, do not continue to reset and seek advice from a trained professional. These RCDs are fitted as a safety mechanism and may indicate a fault or defect with your 240v electrics within the caravan or main supply you are using.

If no fix can be found, contact Enerdrive directly to assist further with diagnosing an issue with the inverter.

If none of these steps finds a resolution, it is recommended to seek professional help from a qualified 240v electrician to determine the issue.